Electronic Discharge Monitoring Reporting (eDMR)

User's Guide

Revised March 22, 2013

Contents

Logging into the System 3

Creating a New eDMR 4

Entering DMR Information 9

Manual Entry 10

Load from File 18

Required Attachments 24

Replacing Attachments 27

Worksheet Certification 30

Submitting the eDMR to DEP 32

Deleting eDMRs Created in Error 36

Contact Information 38

Logging into the System

Website address for electronic discharge monitoring reporting (eDMR):
https://apps.dep.wv.gov/eplogin.cfm

Before you can log into the system, you need to register for a username and password. If you do not have an account, please refer to the "How to Sign Up for an eDMR/ePermitting Login ID and Password" document. If you have a login for ePermitting, you do not need to request a separate production login for eDMR.



NOTE: Once you have successfully entered your login information, any period of inactivity for two hours will log you out of the system.

Creating a New eDMR

After logging in, you will be presented with the **Selection Process** screen. This screen is considered the eDMR **Home** screen and is where you will start to create, continue, or review eDMRs.

Anytime you need to switch to a different eDMR (e.g. a different month for the same facility or an entirely different facility), you can click the **"Return Home"** button at the left to get back to the **Selection Process Home** screen.



Several options are available under the **Process** field:

- **New**: create a new eDMR
- **Continue**: work on a previously created eDMR
- **Review**: bring up a read-only version of a previously submitted eDMR
- **Security**: change your account preferences

You will select the **Office** you intend to create the eDMR for. The common choices will be **Hydrologic Protection Unit (HPU)** or **Water and Waste Management (OWR).**



On the **Applicant** field, select the company or facility that you intend to create the eDMR for. You will only see companies or facilities you have access to.



On the **Type** field, select "**Electronic DMR – eDMR.**"

NOTE: You might see other options here if you have the security rights to create a permit (e.g. ePermitting).



On the **Reference ID** field, please include your permit number and/or general permit registration number as applicable, sample period and year. Examples: WV0023205 August 2012, WVG550987 3rd Qtr 2012, WVG610897 Semi-Annual August 2012.

This will help you easily bring up and review previously submitted eDMRs when needed.

NOTE: If you have more than one NPDES permit ID number and/or general permit registration number, a separate Reference ID should be created for each.



Hit the "**Create New**" button to create the eDMR.



Entering DMR Information

Below are two options for submitting an eDMR.

- Manual Entry- to enter DMR information manually
- Load from File – to upload a file that conforms to the DEP DMR file structure, visit http://www.dep.wv.gov/WWE/permit/npdes/Documents/FileStructure2.pdf.

NOTE: Choose only ONE method for each eDMR.



Manual Entry

Click on "**Add**" beside **"Manual Entry"** to create a new eDMR Worksheet in the **Section List** screen.

NOTE: You need to create a new eDMR Worksheet for each Permit / Outlet combination.



To start entering information, click on the green **"eDMR Worksheet"** link.



NOTE: You can delete unwanted worksheets by clicking on "**Remove**" beside the worksheet link.

You are required to provide information for blue highlighted fields. Any field with a magnifying glass beside it, is a drop-down field, which means if you click on the field, you will be able to choose from a list of options.

Specify the Permit Number, Outlet Number, Type, and the Lab that has performed the analysis for this eDMR. If the Permit Number and/or Outlet Number box doesn't show up, minimize your screen, it's probably setting behind the screen in another window. See page 13 for additional information about entering the laboratory identification.



In order to save data that has been entered, you <u>must</u> click the "**Save Changes**" button **at least every two hours**.



Below are examples of the choices available in the drop-down fields :



Permit – choose the permit you intend to enter information for.

Select a Permit:
WV0021792
WVR100098
WVR100384

Outlet - choose the outlet you intend to enter information for.
NOTE: These outlets are filtered based on the permit you have selected.

ID	Name	Pipe Status
002	EFFLUENT BOD5 SAMPLES SHALL BE COLLECTED AT A LOCA...	Reactivated - 12/27/2005
IU01	ALLEGHENY WOOD PRODUCTS, INC. - REFER TO SECTIONS F....	
IU02	PETERSBURG WTP - REFER TO SECTIONS F.2.A.2 AND F.2.B.2 ...	
IU03	GRANT COUNTY LANDFILL - REFER TO SECTIONS F.2.A.3 AN...	
IU04	REGION VIII SWA - REFER TO SECTIONS F.2.A.4 AND F.2.B.4 F...	
IU05	ADELL POLYMERS - REFER TO SECTIONS F.2.A.5 AND F.2.B.5 ...	Reactivated - 01/09/2006
IU06	HESS OIL COMPANY (FORT HILL EXXON) - REFER TO SECTION...	
IU07	REACTIVATE PIPE AND USE THIS OUTFALL FOR NEXT INDUST...	Inactive - 01/17/2006
S01	SLUDGE	

Lab Performing Analysis – Only certified labs will be available in the drop-down field. Choose the lab that has performed the majority of the analysis. If a different lab has performed analysis for a specific parameter, you will have the opportunity to change the lab information at the parameter level.

Lab ID	Lab Name
313	A & L EASTERN AGRICULTURAL LABORATORIES INC
010	AC & S LABORATORIES
279	ACCULAB II INC
062	ACCULAB INC
329	ACCUTEST LABORATORIES
304	ACCUTEST LABS, SE
280	ADVANCED ANALYTICS LABORATORIES INC
351	ADVENT-ENVIRON

Select **No Flow**, **Not Analyzed**, **Conditional Monitoring**–Not required this period, **Not Quantifiable** or **Other** on the **Type** field. **NOTE:** You also can do this for individual parameters.

- Use **Conditional Monitoring** when you are required to submit an annual certification form and/or at parameter level when monitoring has been waived.
- When choosing **No Flow, Not Analyzed, Conditional Monitoring**–Not required this period, or **Other** select 000 – under **Lab Performing Analysis.**
- You are required to enter a reason if you have selected **Not Analyzed** or **Other**. (Examples: Lab Accident, Flow meter out of service, etc.)
- For facilities registered under the Sewage General Permit less than 50,000 GPD (WVG55 prefix), use **Not Quantifiable** at the parameter level for Total Residual Chlorine in the test flag field *if you have ultraviolet disinfection (uv)*.



Enter the appropriate month in the **Report for the Month of** field and the appropriate year.



The following information is provided to assist you in determining what month you are reporting.

For permitted facilities that are required to submit a discharge monitoring report on a quarterly, semi-annual, or annual basis, the eDMR system will only allow you to submit the data in the month that it is required. Examples:

- **If your permit was effective prior to July 1, 2011 the following will apply:**
  - A quarterly reporting requirement is based on the calendar quarters; therefore, the quarterly discharge monitoring data can only be entered and submitted in eDMR in March, June, September and December.
  - If a permit requires semi-annual or annual reporting of DMR data based on **the effective date of the permit** (Individual Industrial and Municipal permits) the reporting month is as follows:
    - **Effective date** of the permit is prior to the 15th day of a month, the reporting month is determined by counting from the first day of that month forward six months (e.g., if effective date is February 11th, the reporting month is July).
    - **Effective date** of the permit is the 15th day of a month or after, the reporting month is determined by counting from the first day of the following month forward six months (e.g. if effective date is February 17th, the reporting month is August).
  - If a permit requires semi-annual or annual reporting of DMR data based on **the issued (or reissued) date of the permit** (General Permits), the reporting month is as follows:
    - **Issued (or reissued) date** of the permit is prior to the 15th day of a month, the reporting month is determined by counting from the first day of that month forward six months (e.g., if issued or reissued date is February 11th, the reporting month is July).
    - **Issued (or reissued) date** of the permit is the 15th day of a month or after, the reporting month is determined by counting from the first day of the following month forward six months (e.g. if issued or reissued date is February 17th, the reporting month is August).

- **If your permit was effective after July 1, 2011 the following will apply:**
    - A quarterly reporting requirement is based on the calendar quarters; therefore, the quarterly discharge monitoring data can only be entered and submitted in eDMR in March, June, September and December.
    - **For Individual Permits** - If a permit requires semi-annual or annual reporting of DMR data the reporting month is six or twelve months forward from the effective date of the permit (e.g., if the effective date is February 1st, the reporting month is July).
    - **For General Permits** - If a permit registration approval requires semi-annual or annual reporting of DMR data the reporting month is determined by counting from the first day of the following month past the issuance date of the permit (e.g., if the issuance date is February 17th, start your limit report period on March 1st and count forward six months, making the reporting month August).

Please refer to your permit to determine your reporting frequency of sampling analysis data.

Permittees are required to submit their eDMR 20 days following the end of the reporting period. In other words, if your reporting month is August, you have until September 20th to submit your eDMR.

Specify the reporting month and year, and hit the "**Retrieve Parameters**" button.

This will bring up all the parameters that need reporting for the month and year you have specified.



Blue fields indicate the data that MUST be entered for the period you have specified.

When entering your parameter data, if you have a lab that has completed analysis on a single parameter than what you entered at the outlet level, you can change the lab on that single parameter (see diagram below).

- You can mark a parameter as a **No Flow**, **Not Tested**, or **Other**.
- You are required to enter a reason if you have selected **Not Analyzed** or **Other**. (Examples: Lab Accident, Flow meter out of service, etc.)
- You are required to enter a reason if you change the **Measurement Frequency**.



When all the required fields (in blue) are completed, you must mark the **Section Complete.**
All sections of your eDMR need to be marked as **Section Complete** before it can be submitted to DEP.



Click on **"Menu"** to return to the **Section List** screen.



Load from File

Click on "**Add**" to create a new eDMR Load File Worksheet in the **Section List** screen.



Then, click on the "**eDMR Load File Worksheet"** link**.**

NOTE: The eDMR Load File Worksheet function can only accept data in a comma-separated values (CSV) format that conforms to DEP's DMR file structure. The specific requirements for the CSV file can be found at http://www.dep.wv.gov/WWE/permit/npdes/Documents/FileStructure2.pdf.



Click on the "**Attach/View Files**" button to upload a file.



On the **Attach/View Files** pop-up window, "**Browse**" for the file you want to upload, select the file and hit the "**Upload**" button.

Hit the "**Close**" button to close the pop-up window.



The file you have uploaded should now be displayed on the section form.

Click "**View**" to look at and verify the contents of the file. While viewing, you can filter by permit, outlet and sampling date.



Current User: SUPLIDO, REGGIE
Ref. Id: 004 (10/27/2008)
Status: New
Applicant: PETERSBURG, CITY OF
Type: Electronic DMR
Permit No.: New/Pending

eDMR Load File Worksheet

Section Complete | Section Incomplete | Activities | Attachments | Comments | Instructions

#	File Name		Validated
1	southnov.csv	View	✓
2	test1_B.csv	View	✓
3	test1_A.csv	View	✗ Validate

Filter Parameters:

Permit: WV0095869 Outlet: All Go (1)

Permit: WV0095869 Outlet: 001 Sampling Date: 11/30/2006 (2)

Line #	Parameter		Quantity Min	Quantity Avg	Quantity Max	Quantity Units	Quantity Number Exceed.	Other Units Min	Other Units Avg	Other Units Max	Other Units Units	Other Units Number Exceed.	Measurement Frequency	Sample Type
1	1105 Aluminum, Total (As Al)	Reported					0	0.04	0.04	0.04	MG/L	0		Grab
		Permit Limits	N/A	N/A	N/A				0.08	0.14 (3)			Semi-monthly	
2	1045 Iron, Total (As Fe)	Reported					0	0.07	0.105	0.14	MG/L	0		Grab
		Permit Limits	N/A	N/A	N/A				1.42	2.46			Semi-monthly	
3	1055 Manganese, Total	Reported					0	0.02	0.03	0.04	MG/L	0		Grab
		Permit Limits	N/A	N/A	N/A				1	1.73			Semi-monthly	
4	3654400 (4)	Reported					0	8.06	8.08	8.1		0		
		Permit Limits												
5	530 Suspended Solids, Total	Reported					0	< 1	< 1	< 1	MG/L	0		Grab
		Permit Limits	N/A	N/A	N/A				35	70			Semi-monthly	
6	58 Flow	Reported	30	30	30	GPM	0					0		Estimated
		Permit Limits		Rpt Only	Rpt Only			N/A	N/A	N/A			Semi-monthly	

Permit: WV0095869 Outlet: 010 Sampling Date: 11/30/2006

Line #	Parameter		Quantity Min	Quantity Avg	Quantity Max	Quantity Units	Quantity Number Exceed.	Other Units Min	Other Units Avg	Other Units Max	Other Units Units	Other Units Number Exceed.	Measurement Frequency	Sample Type
7	1105 Aluminum, Total (As Al)	Reported					0	0.04	0.05	0.06	MG/L	0		Grab
		Permit Limits	N/A	N/A	N/A				0.08	0.14			Semi-monthly	
8	1045 Iron, Total (As Fe)	Reported					0	0.04	0.045	0.05	MG/L	0		Grab
		Permit Limits	N/A	N/A	N/A				3	5.26			Semi-monthly	
9	1055 Manganese, Total	Reported					0	0.01	0.01	0.01	MG/L	0		Grab
		Permit Limits	N/A	N/A	N/A				2	3.47			Semi-monthly	
10	400 Ph	Reported					0	7.72	7.975	8.23	Std Units	0		Grab
		Permit Limits	N/A	N/A	N/A			6		9			Semi-monthly	
11	530 Suspended Solids, Total	Reported					0	< 1	< 1	< 1	MG/L	0		Grab
		Permit Limits	N/A	N/A	N/A				35	70			Semi-monthly	
12	58 Flow	Reported	5	7.5	10	GPM	0					0		Estimated
		Permit Limits		Rpt Only	Rpt Only			N/A	N/A	N/A			Semi-monthly	

Permit: WV0095869 Outlet: 014 Sampling Date: 11/30/2006

Line #	Parameter		Quantity Min	Quantity Avg	Quantity Max	Quantity Units	Quantity Number Exceed.	Other Units Min	Other Units Avg	Other Units Max	Other Units Units	Other Units Number Exceed.	Measurement Frequency	Sample Type
13	(5) No Flow													

Permit: WV0095869 Outlet: 003 Sampling Date: 11/30/2006

Line #	Parameter		Quantity Min	Quantity Avg	Quantity Max	Quantity Units	Quantity Number Exceed.	Other Units Min	Other Units Avg	Other Units Max	Other Units Units	Other Units Number Exceed.	Measurement Frequency	Sample Type
14	No Flow													

Permit: WV0095869 Outlet: 004 Sampling Date: 11/30/2006

Line #	Parameter		Quantity Min	Quantity Avg	Quantity Max	Quantity Units	Quantity Number Exceed.	Other Units Min	Other Units Avg	Other Units Max	Other Units Units	Other Units Number Exceed.	Measurement Frequency	Sample Type
15	No Flow													

Permit: WV0095869 Outlet: 006 Sampling Date: 11/30/2006

Line #	Parameter		Quantity Min	Quantity Avg	Quantity Max	Quantity Units	Quantity Number Exceed.	Other Units Min	Other Units Avg	Other Units Max	Other Units Units	Other Units Number Exceed.	Measurement Frequency	Sample Type
16	No Flow													

Permit: WV0095869 Outlet: DAC Sampling Date: 11/30/2006

Line #	Parameter		Quantity Min	Quantity Avg	Quantity Max	Quantity Units	Quantity Number Exceed.	Other Units Min	Other Units Avg	Other Units Max	Other Units Units	Other Units Number Exceed.	Measurement Frequency	Sample Type
17	1105 Aluminum, Total (As Al)	Reported Permit Limits	N/A	N/A	N/A		0	0.15 Rpt Only	0.16 Rpt Only	0.17 Rpt Only	MG/L	0	Semi-monthly	Grab

Save Changes | Back | Next | Print | Current Version | Reset

Navigator | Menu | Index | Home | Log Out

This is how the work-in-progress File Upload Viewer will look like.

Legend:

1. Select All or specific Permit – Outlet – Sampling Date combination
2. Viewer will group report by Permit – Outlet – Sampling Date
3. The actual permit limits of each chemical will be shown, along with the limits being reported
4. Chemicals being reported that are not part of the permit will be highlighted in pink.
5. Outlets declared as a "No Flow" will be highlighted in pink.

Click on "**Validate**" to check the file for accuracy.
Depending on the size of the file, validation can take between a few seconds to a few minutes.



A properly validated file will show a green circle with a check on the **Validated** field. Files that did not pass validation will show a red icon. You can click on the "**View Validation Report**" to display the problems encountered in the file.



A sample **Validation Report** is shown below.
Rows that have passed will have a green **"Pass"** beside them.
Rows that were rejected will have details of the problem(s). You will need to correct these rows, then re-upload and re-verify your file.

Records Found: 19

Row: 1 Pass
Row: 2 Fail

'Quantity Average' must be a numeric value, and can not equal zero. If below detectable level, please use '<' (less than) sign for 'Quantity Average Flag' column.

Row #	Sampler ID	Outlet		Sampling Date	Qty Code	Qty Min Flag	Qty Avg Flag	Qty Max Flag	Conc Code	Conc Min Flag	Conc Avg Flag	Conc Max Flag	Sample Freq	Qty Exceed	Rainfall Inch	Frozen Cond	Discharge Flag
	NPDES No	Quality	Mon Loc			Qty Min	Qty Avg	Qty Max		Conc Min	Conc Avg	Conc Max	Sample Type	Conc Exceed	Rainfall Date	Report Freq	
2	060	001		06/30/2008	26		<	<	19		<	<	01/90				
	WV0004740	00310	1				0	4			2	2	24				

Row: 3 Fail

'Quantity Maximum' must be a numeric value, and can not equal zero. If below detectable level, please use '<' (less than) sign for 'Quantity Maximum Flag' column.

Row #	Sampler ID	Outlet		Sampling Date	Qty Code	Qty Min Flag	Qty Avg Flag	Qty Max Flag	Conc Code	Conc Min Flag	Conc Avg Flag	Conc Max Flag	Sample Freq	Qty Exceed	Rainfall Inch	Frozen Cond	Discharge Flag
	NPDES No	Quality	Mon Loc			Qty Min	Qty Avg	Qty Max		Conc Min	Conc Avg	Conc Max	Sample Type	Conc Exceed	Rainfall Date	Report Freq	
3	060	001		06/30/2008	26				19				01/90				
	WV0004740	00340	1				166	0			82	82	24				

Row: 4 Pass
Row: 5 Pass
Row: 6 Pass
Row: 7 Pass
Row: 8 Pass
Row: 9 Pass

Once all the files have passed validation, you must mark the "**Section Complete.**"

NOTE: All the sections need to be marked as complete before they can be submitted to DEP.

Click on **"Menu"** to return to the **Section List** screen.



If you need to replace a file that you have uploaded, please see page 27 for instructions.

Required Attachments

The **eDMR Required Attachments** section is where you upload other documents that need to be submitted.

Municipal facilities may be required to submit a **Sludge Management Report and/or ES-59 Summary of Wastewater Treatment Plant Operations**. Please refer to your permit to determine what you are required to submit by attachment.

Annual certification form, laboratory results, etc. may also be attached.



To upload files, click on the "**Attachments"** button.



On the **Attachments** pop-up window, click "**Browse**" to find the files from your computer that you want to upload. Select the file and hit the "**Upload**" button. Hit the "**Close**" button to close the pop-up window.



If you need to attach additional files, you may do so by selecting the number of additional files you want to attach to the eDMR.



An additional set of rows will then appear at the bottom of the window to let you attach the additional files. Select the **Type** of file you are uploading and enter a short description of the file. Hit **"Browse"** to locate the file you want to upload.



Once all the files have been added, select the "**Upload**" button and hit the "**Close**" button to close the pop-up window.



After closing the **Additional Attachments** screen, you must mark "**Section Complete**" on the **Required Attachments** screen. If you are not required to attach any documents, and have not uploaded any documents on the **eDMR Required Attachments** screen, you still must mark "**Section Complete**." All sections must be marked as complete, before they can be submitted to DEP.

Click on **"Menu"** to return to the **Section List** screen.



Replacing Attachments

To replace a file attachment, go to the **Section List** screen and click on **"eDMR Load File Worksheet"** or **"eDMR Required Attachments."**



On the next screen, click on **"Attachments."**

On the screen that appears, click on the **red lock** under **Action**.



A small blue box appears for you to type a reason. Then click on the **"Ok"** button.



Click on **"Replace this file."**



Click on the **"Browse"** button to find the replacement file.



After you select the file, you must click on the **"Upload"** button.



At this point click on the **"Close"** button.



Worksheet Certification

The **eDMR Worksheet Certification** screen is also known as the **Signature** page.



The **Principal Executive Officer** of the facility must complete this section.



Once all the information has been entered, you must mark the "**Section Complete.**"
NOTE: All sections must be marked as complete, before they can be submitted to DEP.

Click on **"Menu"** to return to the **Section List** screen.



Submitting the eDMR to DEP

After marking all sections complete, a "**Submit Application**" button will appear on the **Section List** screen (see diagram below).

NOTE: Only the users who have security rights to submit applications to DEP will see this button.

Clicking the "**Submit Application"** button requires the user to answer a security question in order to submit the eDMR.



Submitting the eDMR will automatically lock the sections from being changed; however, viewing the sections will still be possible.



Once the eDMR is submitted, DEP and facility personnel involved with processing the eDMR will be notified via e-mail. Any status change on the submitted eDMR will also trigger an e-mail notification.

If you receive an e-mail requesting a correction or clarification of your submitted eDMR, you will have to log into eDMR. On **the Selection Process** screen, choose **Continue** in the drop-down menu, and then select the **Office**, **Applicant** and **Type**. A **Ref. ID** section will appear. Click on the eDMR that needs correction. This will bring you to the **Section List** screen where you will select a worksheet to modify.



Deleting eDMRs Created in Error

An eDMR application that has been created in error can only be deleted by the person who is listed as the Applicant Security for the electronic submission of the eDMR.



The person(s) with these rights can delete an eDMR by bringing up the eDMR on the **Section List** screen. From there, click on the **Delete Application** button on the left side of the screen (shown below).



A pop-up warning will appear. You must complete the information requested on the pop-up and click **Delete**.



A message will then confirm that you have successfully deleted your application.

Contact Information

For individual eDMRs:

Tonya Phillips (304) 926-0499 Ext. 1010 or by e-mail at Tonya.R.Phillips@wv.gov

Megan Smith (304) 926-0499 Ext. 1281 or by e-mail at Megan.D.Smith@wv.gov

For Stormwater eDMRs (WVG61s):

Patrick Burch (304) 926-0499 Ext. 1067 or by e-mail at Patrick.D.Burch@wv.gov

For UIC eDMRs:

Michelle Finney (304) 926-0499 Ext. 1047 or by e-mail at Michelle.L.Finney@wv.gov

For Mining and Reclamation eDMRs:

Angela Dorsey (304) 926-0499 Ext. 1513 or by e-mail Angela.H.Dorsey@wv.gov

Vicki Lucas (304) 926-0499 Ext. 1514 or by e-mail Vicki.E.Lucas@wv.gov

For all other General Permit eDMRs:

Thomas Sowers (304) 926-0499 Ext. 1012 or by e-mail at Thomas.J.Sowers@wv.gov

Backup for all of the above with the exception of mining related eDMRs and current contact for any type not listed above:

Mavis Layton (304) 926-0499 Ext. 1025 or by e-mail at Mavis.L.Layton@wv.gov