




Union Carbide Corporation
A Subsidiary of The Dow Chemical Company
P.O. Box 8004
437 MacCorkle Avenue, SW
South Charleston, WV 25303
USA

CERTIFIED MAIL – RETURN RECEIPT REQUESTED
#7012 2920 0000 2036 6424

May 12, 2015

Mr. William F. Durham, Director
WVDEP Division of Air Quality
601 57th Street
Charleston, WV 25304



Dear Mr. Durham,

Attention: Mr. Steve Pursley

RE: UNION CARBIDE CORPORATION (UCC) – SOUTH CHARLESTON FACILITY
REGULATION 13 PERMIT NUMBER: R13-3025A
GROUNDWATER/SOIL REMEDIATION – MIDDLE ISLAND SECOND SOURCE
REGULATION 13 CLASS I ADMINISTRATIVE UPDATE REQUEST

This letter serves as a request for a Class I Administrative Update to permit no. R13-3025A, for groundwater/soil remediation activities located at South Charleston Plant. The proposed changes do not involve regulatory applicability determinations, or changes associated with decreased monitoring, recordkeeping, or reporting requirements. The following changes are being requested:

1. Condition 4.3.4. states the recordkeeping requirements associated with the electric catalytic oxidizer and refers to the inlet gas temperature. Based on manufacturer's recommendations, the temperature is currently monitored at the actual combustion chamber. Class I Administrative Update R13-3025A reflects the change made previously to permit condition 4.1.4.1., which was issued on February 6, 2015. UCC requests that the recordkeeping requirements 4.3.4.1. and 4.3.4.5. be changed from "inlet gas" to "combustion chamber" for the purpose of clarification and consistency.

4.3.4. The permittee shall maintain the following records relating to the electric catalytic oxidizer.

4.3.4.1. Daily average ~~inlet gas~~ combustion chamber temperature. Said average shall be determined by monitoring the temperature every operating hour when contaminated vent gas is being combusted, then averaging the operating hour readings for each calendar day.

4.3.4.5. Records of oxidizer ~~inlet gas~~ combustion chamber temperature monitoring equipment downtime and corrective actions taken.

Mr. William F. Durham, Director
May 12, 2015
Page Two

If you have any questions regarding this notification, please contact Toby Scholl at (304) 747-5619.

Sincerely yours,



J. M. Raess
WVO Responsible Care Leader

Attachment

cc: Ms. Zelma Maldonado
U.S. EPA Region 3
Air Protection Division (3AP20)
1650 Arch Street
Philadelphia, PA 19103-2029