



west virginia department of environmental remediation
Office of Environmental Remediation

VRP Project #: 15017
Brownfield Site: Yes [ ] No [x]
Report Date: 12-10-15
Page 1 of 3

OFFICE OF ENVIRONMENTAL REMEDIATION
VOLUNTARY REMEDIATION PROJECT
SITE VISIT/INSPECTION REPORT

APPLICANT

LRS

Table with 2 columns: APPLICANT and LRS. Rows include Name, Address, City, State, ZIP, Phone, and Contact information for Freedom Industries and Matt Ford.

LOCATION

Table with 2 columns: FACILITY and STREET ADDRESS. Rows include Facility name, City, County, Date of Visit, Time In, and Time Out.

Form containing site status (Abandoned [x], Active [ ]), UST's (Existing [ ], Former [x]), surface soil staining (Yes [ ], No [x]), and surrounding land use (Residential [x], Commercial [x], Industrial [ ], etc.).

COMMENTS

Arrived and signed in at Freedom Industries AST release site @ 9:31 am. MCHM smell was noticeable as soon as I stepped out of the Jeep. A truck load of stockpiled soil was undergoing decontamination (decon) and ready to head to landfill. This was the 8th truck load of the day (by~ 9:30 am). By 10:17 am, 10th truck load of contaminated soil was on its way out. Excavation of MCHM/PPH contaminated soil continues today in Area 1B. The plan for today is to finish excavation in Area 1B, begin excavation in Area 2 which had been covered by stockpiles and finish Area 2 tomorrow. Matt Ford, Lafe Kunkel, Sotero Svingos and Jared Sommers of CORE Environmental on-site, Paul Peter of McIntosh Associates (air monitoring consultant) on-site and all SPSI workers on-site.

Handwritten signature: Ben S. Svingos

WVDEP/OER Project Manager: \_\_\_\_\_

Date: December 10, 2015

1. @ 9:34 AM, the 8<sup>th</sup> truck load of stockpiled soil on its way to the landfill.



3. Truck decon station/personnel on the left and sampling station/ personnel on the right



2. @ 10:11 am, stockpiled soils in Area 2 continued to be removed.



4. Additional photo - loading truck with the stockpiled soil in Area 2



5. Stockpiled soil in Area 2 being loaded into truck - view from Barlow Drive.

