



VRP Project #: 15017  
 Brownfield Site: Yes  No   
 Report Date: 3/03/16  
 Page 1 of 2

**OFFICE OF ENVIRONMENTAL REMEDIATION**  
**VOLUNTARY REMEDIATION PROJECT**  
**SITE VISIT/INSPECTION REPORT**

**APPLICANT**

**LRS**

NAME: : <b>Freedom Industries</b>			NAME: <b>Matt Ford</b>			LRS# <b>240</b>					
ADDRESS: <b>1015 Barlow Drive</b>			ADDRESS: <b>533 North Jefferson Street, Suite 3</b>								
CITY: <b>Charleston</b>		STATE: <b>WV</b>		ZIP: <b>25311</b>		CITY: <b>Lewisburg</b>		STATE: <b>WV</b>		ZIP: <b>24901</b>	
PHONE: <b>(304)720-2312</b>						PHONE: <b>(304) 520-4260</b>					
CONTACT: <b>Robert Johns, Spill Claim Plan Administrator</b>											

**LOCATION**

FACILITY: : <b>Freedom Industries</b>			STREET ADDRESS: : <b>1015 Barlow Drive</b>								
CITY: <b>Charleston</b>			COUNTY: <b>Kanawha</b>			PHONE: ( )					
DATE OF VISIT: <b>March 02, 2016</b>			TIME IN: <b>3:08</b>			TIME OUT: <b>3:42</b>					

**SITE STATUS:** Abandoned  Active  | **UST's:** Existing  Former  | **SURFACE SOIL STAINING:** Yes  No   
**SURFACE WATER ON OR ADJACENT TO PROPERTY:** Yes  No  | **EXISTING MONITORING WELLS:** Yes  No

Existing Structures Including Dimensions and Use: Former/current office building composed of offices, small coal testing lab and storage approximately 125' Length x 85' wide x 30' in height. Garage and maintenance/vehicle storage building approximately 225' in length x 55' wide x 20' in height.

Chemicals of Potential Concern: 4-methylcyclohexanemethanol (MCHM), propylene glycol phenyl ether (PPH), calcium chloride, ethylene glycol, glycerin, polychlorinated biphenyls (PCB's), lead, petroleum hydrocarbons, volatile organic compounds (VOC's) and semi-volatile organic compounds (SVOC's)

<b>DRINKING WATER SOURCE:</b> GW <input type="checkbox"/> Public <input checked="" type="checkbox"/> Other			<b>SURROUNDING LAND USE:</b> Residential <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Industrial <input type="checkbox"/> Recreational <input type="checkbox"/> Agricultural <input type="checkbox"/> Other <input type="checkbox"/>								
---	--	--	--	--	--	--	--	--	--	--	--

**OTHER AREAS OF CONCERN:**

**COMMENTS**

Time in at Freedom was 15:08.

Personnel on site were were Kinder Tuckwiller of Core Environmental, and Chuck Devine who was operating the backhoe equipment. Brick and block were being excavated and piled until it could be determined if any contamination was present.

No water was removed today from site.

Water sample taken from sump 8 showed elevated levels of MCHM in area 4. Soil from area 4 was being stockpiled until it could be removed. No MCHM odor was detected from stockpiled soil, but temperatures were low during site visit which may have helped keep odor encapsulated. I could intermittently smell a faint petroleum odor.

Tent was removed from sump 8.

Departed site at 15:42.

*Danae Hight*

**Signature:** \_\_\_\_\_ **Date:** 3/03/16



Figure 1: Stockpiled soil from area 4



Figure 4: area 4 soil removal



Figure 2: Close-up of stockpiled soil from area 4 on right of excavator, and stockpiled bricks and block on left



Figure 3: Sump 8 with plastic removed

Signature: \_\_\_\_\_ Date: \_\_\_\_\_