



OFFICE OF ENVIRONMENTAL REMEDIATION
VOLUNTARY REMEDIATION PROJECT
SITE VISIT/INSPECTION REPORT

APPLICANT

LRS

NAME: : Freedom Industries			NAME: Matt Ford			LRS# 240		
ADDRESS: 1015 Barlow Drive			ADDRESS: 533 North Jefferson Street, Suite 3					
CITY: Charleston		STATE: WV	ZIP: 25311		CITY: Lewisburg		STATE: WV	ZIP: 24901
PHONE: (304)720-2312			PHONE: (304) 520-4260					
CONTACT: Robert Johns, Spill Claim Plan Administrator								

LOCATION

FACILITY: : Freedom Industries			STREET ADDRESS: : 1015 Barlow Drive					
CITY: Charleston			COUNTY: Kanawha			PHONE: ()		
DATE OF VISIT: March 24, 2016			TIME IN: 15:05			TIME OUT: 15:57		

SITE STATUS: Abandoned Active | **UST's:** Existing Former | **SURFACE SOIL STAINING:** Yes No
SURFACE WATER ON OR ADJACENT TO PROPERTY: Yes No | **EXISTING MONITORING WELLS:** Yes No

Existing Structures Including Dimensions and Use: Former/current office building composed of offices, small coal testing lab and storage approximately 125' Length x 85' wide x 30' in height. Garage and maintenance/vehicle storage building approximately 225' in length x 55' wide x 20' in height.

Chemicals of Potential Concern: 4-methylcyclohexanemethanol (MCHM), propylene glycol phenyl ether (PPH), calcium chloride, ethylene glycol, glycerin, polychlorinated biphenyls (PCB's), lead, petroleum hydrocarbons, volatile organic compounds (VOC's) and semi-volatile organic compounds (SVOC's)

DRINKING WATER SOURCE: GW <input type="checkbox"/> Public <input checked="" type="checkbox"/> Other	SURROUNDING LAND USE: Residential <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Industrial <input type="checkbox"/> Recreational <input type="checkbox"/> Agricultural <input type="checkbox"/> Other <input type="checkbox"/>
---	--

OTHER AREAS OF CONCERN:

COMMENTS

Time in at Freedom was 15:05.

Personnel on site were were Kinder Tuckwiller of Core Environmental, Lance Wilcox, Gary Houseman and Larry Gaffta who were operating the backhoe and bobcat in tandem placing additional concrete blocks at base of toe.

One backhoe was being driven off site on my arrival.

Grass mats are in place with along with bales of straw dotting location.

Departed site at 15:57.

Danae Hight

3/25/16

Signature: _____ **Date:** _____



Figure 1: Grass Mats in place



Figure 4: Close-up of grass mat



Figure 2: Placing block at toe



Figure 5: Straw bales



Figure 3: Guiding block into place



Figure 6: Bobcat bring block to excavator

Signature: _____ Date: _____

Charleston – Original

Copy – Project Manager

Copy - Applicant