



---

west virginia department of environmental protection

---

Office of Oil and Gas  
601 57th Street SE  
Charleston, WV 25304  
(304) 926-0450  
(304) 926-0452 fax

Earl Ray Tomblin, Governor  
Randy C. Huffman, Cabinet Secretary  
www.dep.wv.gov

August 21, 2015

## FINAL INSPECTION REPORT

### Fracture Permit Cancelled

EQT PRODUCTION COMPANY,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-3301114, issued to EQT PRODUCTION COMPANY, and listed below has been received in this office. The permit has been cancelled as of 8/20/2015.

A handwritten signature in blue ink, appearing to read 'James Martin', is positioned above the printed name.

James Martin  
Chief

Operator: EQT PRODUCTION COMPANY  
Operator's Well No: MCQUAID 151381  
Farm Name: LOAR, JAMES W., ET UX  
**API Well Number: 47-3301114**  
Date Issued: 05/29/2008

Date Cancelled: 08/20/2015

Promoting a healthy environment.

INSPECTORS PERMIT SUMMARY FORM

AGE 1

GPS YES  NO

DATE STARTED/LOCATION:  API #: 47-33-1114 WELL NO. McQuaid 151381  
 DRILLING COMMENCED:  OPERATOR: EQT Production Company  
 ID DATE:  DEPTH:  FARM: Loar, James W, ET UX  
 WATER DEPTHS  COAL DEPTHS

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:  
 A. CONSTRUCTION YES  NO  (2 PTS) B. DRILLING YES  NO  (2 PTS) (4 PTS) \_\_\_\_\_  
 2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES  NO  (4 PTS) (4 PTS) \_\_\_\_\_  
 3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES  NO  (4 PTS) (4 PTS) \_\_\_\_\_

4. CONSTRUCTION:  
 WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?  
 A. ROAD DITCHES 1  2  3  4  (PTS) B. CROSS DRAINS 1  2  3  4  5  (PTS)  
 C. CULVERTS 1  2  3  4  5  (PTS) D. CREEK CROSSINGS 1  2  3  (PTS)  
 E. DIVERSION DITCHES 1  2  3  (PTS) F. BARRIERS 1  2  3  (PTS)  
 G. TEMPORARY SEEDING YES  NO  (10 PTS) POINTS AVAILABLE FOR QUESTION 4: (33 PTS) \_\_\_\_\_

5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES  NO  (2 PTS) (2 PTS) \_\_\_\_\_  
 6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES  NO  (9 PTS) (9 PTS) \_\_\_\_\_

7. RECLAMATION:  
 A. ROADWAY 1  2  3  (PTS) B. LOCATION 1  2  3  (PTS)  
 C. PITS 1  2  3  (PTS) D. PIPELINES 1  2  3  (PTS)  
 E. BANK DIKES 1  2  3  (PTS) F. API INSTALLED YES  NO  (3 PTS)  
 G. ADEQUATE SEEDING MATERIALS 1  2  3  (PTS)  
 H. WAS SEED BED ADEQUATE 1  2  3  (PTS) POINTS AVAILABLE FOR QUESTION 7: (24 PTS) \_\_\_\_\_

8. WAS RECLAMATION COMPLETED WITHIN:  
 6 MTHS OF TD \_\_\_ 6 PTS ONLY; 4 MTHS OF TD \_\_\_ 12 PTS ONLY; 2 MTHS OF TD \_\_\_ 19 PTS ONLY.  
 MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS) \_\_\_\_\_

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: \_\_\_\_\_

INSPECTIONS:

Fracture Permit Cancel

**Received**

8/20/2015  
DATE RELEASED

S. D. Whitte  
INSPECTOR

AUG 20 2015